



KIRBY INLAND MARINE, LP 55 WAUGH DRIVE, SUITE 1000 HOUSTON, TEXAS 77007 DEZAVALA FLEET SHORELINE REPAIRS AT CARPENTER'S BAYOU & BUFFALO BAYOU IN CHANNELVIEW, HARRIS COUNTY, TEXAS

DATE: SEPTEMBER 6, 2012 SHEET: 4 OF 6

## ND GEOTUBE SHORELINE PROTECTION 5 1 \* 12.00 1/45 MATCHLINE SEE DWG. 4 OF 6 MATCHLINE SEE DWG. 4 OF 6

# CONSTRUCTION NOTES

FURNISH AND INSTALL: NEW 20' WIDE X 550'
LONG, 34' CIRCUMFERENCE, CONTINUOUS
GT1000M GEOTUBE CONTAINER WITH GT500
SHROUD. INSTALL 20' WIDE SCOUR APRON,
GT500 POLYPROPYLENE, PERFORM ONLY
EXCAVATION NECESSARY TO CREATE THE
ALIGAMENT FOR THE NEW GEOTUBE. THIS
SHOULD INCLUDE A LEVEL, STRAIGHT, SHALLOW
SWALE AS REQUIRED. REFER TO THESE
DRAWINGS AND ATTACHED SPECIFICATIONS.
FURNISH AND INSTALL: STONE RIPRAP IN AREA
SHOWN (50–250 LBS.) (NOTE: PETRO-FLEX
MAT MAYBE SUBSTITUTED IN THE AREA
COVERING THE DISCHARGE PIPE WITH ENGINEER
APPROVAL.)

COVERING THE DISCHARGE PIPE WITH ENGINEER APPROVAL.)
FURNISH AND INSTALL: 50LF PIPE AT 1% MIN. SLOPE. PROVIDE ALL MATERIALS NECESSARY
TO TIE-IN TO THE EXISTING PIPE. DEMO EXISTING CONCRETE STRUCTURE AS REQUIRED. THE OUTFALL PIPE USED FOR THE EXTENSION WILL BE THE SAME SIZE AND TYPE AS EXISTING. PROVIDE ADEQUATE COMPACTION OF NEW BACKFILL BEFORE THE NEW OUTFALL PIPE IS INSTALLED. COVER WITH PETROFLEX MAT AS SHOWN.

CONSTRUCT REINFORCED CONCRETE PIPE COLLAR.

EXISTING TIMBER PILES TO BE REMOVED TO 4'

EXISTING TIMBER PILES TO BE REMOVED TO 4'
BELOW GRADE (MINIMUM) AND DISPOSED OF,
AFTER THE GEOTUBE AND SCOUR APRON ARE
IN PLACE AND FILLED, APPROXIMATELY 1,800
CU. YOS. OF SAND BACKFILL WILL BE PLACED
FROM JUST BELOW THE BACKSIDE CURVE OF
THE GEOTUBE AT ELEVATION +5.0' AND SLOPE
UPWARD TO MATCH EXISTING GRADE AT
ELEVATION +5.0'. DO NOT DISTURBE THE
ELEVATION +5.0'. DO NOT DISTURBE THE UPWARD TO MATCH EXISTING GRADE AT ELEVATION +6.0°. DO NOT DISTURB THE ELISTING VEGETATION ANYMORE THAN NECESSARY. COMPACT TO 90%. FURNISH AND PLACE 2" TOPSOIL ON ALL AREAS WHICH WERE BACKFILLED AND FEATHER OUT TO TIE-IN TO ADJACENT EXISTING VEGETATED AREAS. FURNISH AND INSTALL GRASS SEEDS, MIRAFI FW-700 GEOTEXTILE FABRIC, HYDROMULCH WITH 70/30 WOOD/PAPER BLEND MULCH, BERMUDA, MILLET, MICROBES, FERTILIZER, TACKFIER, AND CURLEX II EROSION CONTROL BLANKET. WATER AS NECESSARY TO START SEED GERMINATION.





KIRBY INLAND MARINE, LP 55 WAUGH DRIVE, SUITE 1000 HOUSTON, TEXAS 77007

PURPOSE:

DEZAVALA FLEET SHORELINE REPAIRS AT CARPENTER'S BAYOU & BUFFALO BAYOU IN CHANNELVIEW, HARRIS COUNTY, TEXAS

DATE: SEPTEMBER 6, 2012 SHEET: 5 OF 6





NOTE: ELEVATIONS BASED ON MEAN LOW TIDE (MLT) DATA. HIGH TIDE LINE (HTL) ELEVATION IS APPROXIMATE. MEAN HIGH WATER (MHW) ELEVATION IS BASED ON COOPS/NGS ELEVATION DATA AT THE LYNCHBURG LANDING STATION ID 8770733 IN SAN JACINTO, TEXAS.

SCOUR APRON (AS SHOWN ON DWGS.) MLT WATER ELEV: 0.00

Texas Gulf Engineering, LLC CIVIL . MARINE . STRIICTURAL LAKE JACKSON OFFICE HOUSTON OFFICE

122 WEST WAS, 9011FE 306

1AKE JACKSON, TEXNS 77556

TOLE (979)285-3400 | Tac: (979)285-3400 | Tac: (979)285-3400 | Tac: (713)455-1110 | Tac: (713)455-1120

KIRBY INLAND MARINE, LP 55 WAUGH DRIVE, SUITE 1000 HOUSTON, TEXAS 77007

PURPOSE:

DEZAVALA FLEET SHORELINE REPAIRS AT CARPENTER'S BAYOU & BUFFALO BAYOU IN CHANNELVIEW, HARRIS COUNTY, TEXAS

DATE: SEPTEMBER 6, 2012 SHEET: 6 OF 6

SNG-2008-00941